

APPLIED *OCCUPATIONAL AND ENVIRONMENTAL HYGIENE*

In 1993, U.S. Navy submarine crews began to notice yellowing of the bulkheads and other structures during underway periods and sea trials. The yellowing was reported to General Dynamics Electric Boat Division (EBD) as a failure of the paint system.

In 1994, U.S. Navy submarine crews began to notice yellowing of the bulkheads and other structures during underway periods and sea trials. The yellowing was reported to General Dynamics Electric Boat Division (EBD) as a failure of the paint system.

**COPYRIGHT c 2000 APPLIED
INDUSTRIAL HYGIENE**

In a 1970 study, Holder et al. reported on
excretion of DBNP. *Italic*

