

Iron Models **NOT** Recommended For Loft & Lie Adjustment

Ping Maximum Lie Angle Adjustability

MODEL	ADJUSTABILITY	RELEASE REQUIRED
i20 irons	5 color codes	no
G20 irons	5 color codes	no
S56 irons	5 color codes	no
Anser wedges	5 color codes	no
Anser irons	5 color codes	no
Tour-S wedges	5 color codes	no
K15 irons	5 color codes	no
Faith irons	5 color codes	no
i15 irons	5 color codes	no
G15 irons	5 color codes	no
Rapture V2 irons	5 color codes	no
S57 irons	4 color codes (4°)	no
i10- irons	5 color codes	no
G10 irons	5 color codes	no
Rhapsody irons	5 color codes	no
S58 irons	4 color codes (4°)	no
Tour W (brushed slvr)	4 color codes	yes
Tour W (blk nickel)	3 color codes	yes
i5 irons	5 color codes	no
G5 irons	5 color codes	no
Rapture irons	5 color codes	no
iwedge	2 color codes (2°)	yes
Tour Wdg (blk nickel)	3 color codes	yes
Tour Wedge	3 color codes	yes
Ping wedges	2 color codes (2°)	yes
S59/S59 Tour irons	4 color codes (4°)	no
G2 irons	5 color codes	no

Ping Maximum Lie Angle Adjustability

MODEL	ADJUSTABILITY	RELEASE REQUIRED
i3+/i3+ Blade irons	2 color codes (2°)	yes
i3 irons Blade/O Size	2 color codes (2°)	yes
ISI/ISI-N (Cpp./Nkl)	none	n/a
ISI-S/ISI-K (Steel)	2 color codes (2°)	yes
ZING2 (Copper)	none	n/a
ZING2 (Steel)	2 color codes (2°)	yes
ZING (Steel or Cppr)	none	n/a
EYE2/EYE2+ < 10 yr	4 color codes (4°)	no
EYE2/EYE2+ 10-15 yr	2 color codes (2°)	yes
EYE2 (Copper)	none	n/a
EYE	none	n/a
KARSTEN I-IV	none	n/a
Moxie irons	none	n/a